



Map sc9.8: Evans, Charlotte Vale, Eglinton Catchment Soil Erosion

Area - 85, 222 ha



CTLD Sub-Catchments



SOURCES
This map has been compiled from data supplied by the Department of Infrastructure, Planning & Natural Resources (formerly DLWC)

DISCLAIMER
This map has been compiled from various sources and the Central Tablelands District Landcare Management Committee accept no responsibility for any injury, loss or damage arising from its use, or errors, or omissions therein.

- Localities
- ▬ Drainage
- ▬ Infrastructure
- ▬ Highway
- ▬ Main Road
- ▬ Connector Road
- ▬ Other Road
- ▬ Heavy Rail
- ▬ Pipeline (Natural Gas)
- ▬ Transmission Line (Electrical)
- Gully Erosion**
- ▬ Minor
- ▬ Moderate
- ▬ Severe
- ▬ Streambank
- ▬ Very Severe
- Other Erosion**
- ▬ No Appreciable Erosion
- ▬ Minor Sheet & Rill
- ▬ Moderate Sheet & Rill
- ▬ Severe Sheet & Rill
- ▬ Very Severe Sheet & Rill
- ▬ Soil Debris Avalanche
- ▬ Salting
- ▬ Mass Movement Slump

0 2 4 6 8 10 Kilometres