



Map sc10.8: Abercrombie River Catchment

Soil Erosion

Area - 100,275 ha



- Localities
- Catchment
- ▬ Drainage Infrastructure
- ▬ Main Road
- ▬ Connector Road
- ▬ Other Road
- Gully Erosion
- ▬ Minor
- ▬ Moderate
- ▬ Severe
- ▬ Streambank
- ▬ Very Severe
- Other Erosion
- No Appreciable Erosion
- Minor Sheet & Rill
- Moderate Sheet & Rill
- Severe Sheet & Rill
- Very Severe Sheet & Rill
- Soil Debris Avalanche
- Salting
- Mass Movement Slump



CTL D Sub-Catchments

SOURCES
 This map has been compiled from data supplied by the Department of Infrastructure, Planning & Natural Resources (formerly DLWC)

DISCLAIMER
 This map has been compiled from various sources and the Central Tablelands District Landcare Management Committee accept no responsibility for any injury, loss or damage arising from its use, or errors, or omissions therein.

