



Map sc7.8: Fish River Catchment Soil Erosion


Area - 129,335 ha



CTLD Sub-Catchments



- Localities
- Catchment
- ▬ Drainage
- Water Bodies
- Infrastructure
- ▬ Highway
- ▬ Main Road
- ▬ Connector Road
- ▬ Other Road
- ▬ Heavy Rail
- ▬ Pipeline (Natural Gas)
- ▬ Transmission Line (Electrical)
- Gully Erosion
- ▬ Minor
- ▬ Moderate
- ▬ Severe
- ▬ Streambank
- ▬ Very Severe
- Other Erosion
- No Appreciable Erosion
- Minor Sheet & Rill
- Moderate Sheet & Rill
- Severe Sheet & Rill
- Very Severe Sheet & Rill
- Soil Debris Avalanche



SOURCES

This map has been compiled from data supplied by the Department of Infrastructure, Planning & Natural Resources (formerly DLWC)

DISCLAIMER

This map has been compiled from various sources and the Central Tablelands District Landcare Management Committee accept no responsibility for any injury, loss or damage arising from its use, or errors, or omissions therein.

