





Map sc8.8: Campbells River Catchment Soil Erosion

Area - 110,520 ha



- Localities
- Catchment
- ▬ Drainage
- ▬ Infrastructure
- ▬ Main Road
- ▬ Connector Road
- ▬ Other Road
- ▬ Pipeline (Natural Gas)
- ▬ Transmission Line (Electrical)
- Gully Erosion
 - ▬ Minor
 - ▬ Moderate
 - ▬ Severe
- ▬ Streambank
- ▬ Very Severe
- Other Erosion
 - No Appreciable Erosion
 - Minor Sheet & Rill
 - Moderate Sheet & Rill
 - Severe Sheet & Rill
 - Very Severe Sheet & Rill
 - Soil Debris Avalanche
 - Mass Movement Slump

CTLD Sub-Catchments



SOURCES
This map has been compiled from data supplied by the Department of Infrastructure, Planning & Natural Resources (formerly DLWC)

DISCLAIMER
This map has been compiled from various sources and the Central Tablelands District Landcare Management Committee accept no responsibility for any injury, loss or damage arising from its use, or errors, or omissions therein.